4th qrt inspect 1999

0027

Copy from AC7/015/002 #6

POND INSPECTION REPORT

POND: Sediment

LOCATION: JB King mine

ITEM	REMARKS
(1) Potential Safety Hazards	None
(2) Slope Stability	Good
(3) Erosion	very little
(4) Construction and Maintenance Performance Standards	Good
(5) Recommendations/Comments	pond 1/3 full

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Jim Blackburn

10/10/99
Date

OCT 15 1999

Sensor Services
1 - Phone 839-1026
UTAH 84654

SALINA, UT
OCT 12
1999
PM
84654

33 USA

Atten
Susan White

Div of Oil Gas & Mining
1594 west North temple
Suite 1210
Box 145801
Salt Lake City. Ut
84114-5801