10-13-87 0008

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh

inspection report

Permit No. INA/015/004

Inspection Date Sept 3, 1987

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State UT Zip 84501

Mine Huntington #4 ☐ Surface ☒ Underground ☐ Other

County ~~Carbon~~ Emery State UT

Company Official(s) None

State Official(s) John Whitehead, Lowell Braxton, Sue Linner

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 8-27-87 Weather conditions partially cloudy, cool

Acreage ~~125~~ 2600 ☒ Permitted 12.5 ☒ Disturbed 12.0 ☒ Regraded 12.5 ☒ Seeded 12.5 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☑	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☑	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. IAA/015/004

Inspection Date 9/3/87

Please number comments to correspond with topics on previous page.

3) The small amount of topsoil stored on site for final reclamation of the sediment ponds is well vegetated and appears stable

4) The Lower yard main channel appears stable thus far with some deposition of fines in the flat area before the channel drops into the sediment pond

Copy of report mailed to Dan Guy BCCC Brian Smith OSM

Copy of report given to

Inspector's signature John J Whitehead 10/12/87 No. 5

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049