0013

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/004
Inspection Date 5/12/87

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Utah Zip 84501
Mine Huntington Canyon #4 ☐ Surface ☐ Underground ☒ Other
County Emery State
Company Official(s) Ken Flecke
State Official(s) Wm. J Malencik
Time of inspection 7:30 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 4/27/87 Weather conditions Clear/Cool
Acreage 2600 ☑ Permitted 12.5 ☑ Disturbed 12 ☑ Regraded 12 ☑ Seeded 12.5 ☑ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☐	☐	☐	☐
c. Sediment ponds and impoundments	☒	☐	☐	☐
d. Other sediment control measures	☒	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 5/12/87

Please number comments to correspond with topics on previous page.

Introduction: The entire mine site had received a light rain on 5/11/87. While the top inch of soil was moist from the rain, no evidence of runoff was observed. Walked over both the upper & lower sites.
With the exception of the revegetation comments noted herein, all items checked and not commented on were in substance the same as documented in the previous report of 4/27/87.

{13} Revegetation looks good on both the upper and lower sites. The seeded species both grass and forbs are established and making good growth. The rooted plant stock are likewise making a good growth start. The Mtn. Mahogany looks most promising of the "rooted stock" species that were planted. Numerous elk tracks were observed on the upper site. Most of the tracks were made when the soil was very moist, resulting in hoof depressions.

The seeding on the road ripped areas has become more evident, especially in the upper areas.

Willow cuttings adjacent to the pump house site are growing.

Copy of report mailed to DONNA GRIFFIN, OSM; DAN GUY, BCCC

Copy of report given to JOE HELFRICH, JOHN WHITEHEAD, DOGM

Inspector's signature Tom J. Malencik 5/18/87 No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE