0024

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gdh gm

inspection report

Permit No. INA/015/004

Inspection Date FEB. 9, 1988

Permittee/Operator Name BEAVER CREEK COAL COMANY

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine HUNTINGTON CANYON #4 ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) DAN GUY

State Official(s) PAMELA GRUBAUGH-LITTIG and TOM MUNSON

Time of inspection 8:00 ☑ a.m. ☐ p.m. to 9:15 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete

Date of last Inspection ~~12/17 or 22/87~~ JANUARY 13, 1988 Weather conditions SUNNY AND COLD (12°F)

Acreage 2600 ☐ Permitted 12.5 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 12.5 ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date FEB. 9, 1988

Please number comments to correspond with topics on previous page.

General Comment: Drifting and compacted snow prevented vehicle access to the reclaimed mine site. Inaccessible.

4c. Surface Water Monitoring:
The water monitoring plan was amended and approved 3/16/87. Reports were adequately submitted for the four quarters of 1987. The surface water monitoring data collection is being improved. Revised water monitoring sheets are being prepared. These sheets will include a master sheet and frequency of sampling. Additionally, a separate sampling point sheet will be prepared with the ID#, frequency and parameters. These revised sheets will be submitted with the first quarter (1988) H,O monitoring data for Huntington #4 by 3/31/88.

14. Subsidence – An approval letter from DOGM (12/8/87)

Copy of report mailed to DAN GUY, BLM

Copy of report given to BRIAN SMITH, OSM; JOE HELFRICH, DOGM

Inspector's signature [signature] No. #20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date FEB. 9, 1988

Please number comments to correspond with topics on previous page.

essentially releases BCC from further subsidence monitoring (for HUNTINGTON #4). There were 3 conditions that must be addressed. Dan Guy stated that the replies would be submitted by 2/19/88 to the Division for these subsidence clarification requests.

Copy of report mailed to DAN GUY, BCC

Copy of report given to BRIAN SMITH, OSM; Joe Helfrich, DOGM

Inspector's signature [signature] No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049