11-13-89 #095 0003

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340



# inspection report

Permit No. INA/015/004
Inspection Date Nov. 9, 1989

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. Box 1378
City Price State UT Zip 84501
Mine Hiawatha #4 ☐ Surface ☒ Underground ☐ Other
County Emery State UT
Company Official(s) None
State Official(s) Bill Wakmack
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection Oct. 4, 1989 Weather conditions Clear & light breeze
Acreage 2600 ☒ Permitted 12.5 ☒ Disturbed 12 ☒ Regraded 12 ☒ Seeded 12.5 ☒ Bonded
Enforcement Action None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☒ | ☐ | ☐ | ☒ |
| 3. Topsoil | ☒ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| a Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| b Diversions | ☒ | ☐ | ☐ | ☐ |
| c Sediment ponds and impoundments | ☒ | ☐ | ☐ | ☐ |
| d Other sediment control measures | ☒ | ☐ | ☐ | ☐ |
| e Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| f Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☐ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☐ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☐ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☒ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| — Construction | ☐ | ☐ | ☐ | ☐ |
| — Drainage controls | ☐ | ☐ | ☐ | ☐ |
| — Surfacing | ☐ | ☐ | ☐ | ☐ |
| — Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☒ | ☐ | ☐ | ☒ |

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ILA/015/004

Inspection Date Nov. 9, 1989

Please number comments to correspond with topics on previous page.

2) SIGNS HAVE BEEN PLACED TO IDENTIFY SURFACE WATER MONITORING LOCATIONS. WITH THE EXCEPTION OF THE FLOWING CREEK ACROSS FROM THE SEDIMENT PONDS, MONITORING STATIONS WERE DRY & DID NOT SHOW ANY EVIDENCE OF RECENT PRECIPITATION. OTHER MINE I.D. SIGNS WERE IN PLACE AS REQUIRED.

18. THE PERIMETER FENCES APPEARED IN GOOD REPAIR & DID NOT SUFFER ANY VANDALISM DURING THE RECENT BIG GAME HUNT. HOWEVER, A FEW STRANDS OF barbed wire are loose at the lower area near the gate.

Copy of report mailed to SLC : Joe Helfrich (DOGM), Brian Smith (OSM)

Copy of report given to BCCC for Dan Guy, PFO

Inspector's signature William A. Warmack 11/9/89 No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE



an equal opportunity employer