9-19-89 0005

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RUS

inspection report

Permit No. INA/015/004

Inspection Date SEPT 14 & 15, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UT Zip 84501

Mine HUNTINGTON #4 ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) JAY MARSHALL

State Official(s) BILL WARMACK 1:00 - 3:00 pm (14th)

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection AUG 9, 1989 Weather conditions CLEAR & WARM

Acreage 2600 ☒ Permitted 12.5 ☒ Disturbed 12 ☒ Regraded 12 ☒ Seeded 12.5 ☒ Bonded

Enforcement Action NOV 89-33-2-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☒	☐
b. Diversions	☒	☐	☐	☐
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☒	☐	☒
f. Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☒	☐
b. Drainage controls	☒	☐	☐	☐
c. Surfacing	☐	☐	☒	☐
d. Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 9/14 & 15/89

Please number comments to correspond with topics on previous page.

GENERAL: COMPANY OFFICIALS WERE NOT PRESENT DURING THE FIELD INSPECTION ON SEPT. 15. MR. JAY MARSHALL ASSISTED DURING THE RECORDS REVIEW ON SEPT. 14. DIVISION HYDROLOGIST ISSUED NOV 89-33-2-1 FROM THE SLC OFFICE ON SEPT. 14, 1989.

1. PERMITS: THE PERTINENT MINE RECORDS WERE REVIEWED & IN ORDER. A COPY OF THE BOND & INSURANCE DOCUMENTS WAS AVAILABLE; THE DEPT. OF HEALTH INACTIVATED THE UPDES PERMIT ON MAY 1, 1989.

4C. SED PONDS: FIRST & SECOND QUARTER BMP INSPECTIONS WERE COMPLETE, NO PROBLEMS WERE NOTED. AS-CONSTRUCTED DRAWING (PLATE 7-6) CERTIFIED SEPT. 1, 1988. POND CELLS WERE DRY, HOWEVER, GUIDELINE DID NOT INDICATE ANY DISCHARGE HAD OCCURRED.

Copy of report mailed to

Copy of report given to

Inspector's signature UWAW 9/18/89 No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 9/14 & 15/89

Please number comments to correspond with topics on previous page.

4d. OTHER SED CONTROLS: AT THE TIME OF THIS INSPECTION, ALL SILT FENCES WERE IN GOOD REPAIR & FUNCTIONING PROPERLY.

4e. WATER MONITORING: NOV 89-33-2-1 WAS ISSUED FOR FAILURE TO MONITOR SURFACE & GROUNDWATER STATIONS IN ACCORDANCE WITH THE APPROVED PLAN. TOTAL SUSPENDED SOLIDS (TSS) WAS NOT REPORTED IN THE SECOND QUARTER WATER MONITORING DATA. THE OPERATOR IS REQUESTED TO COMPLY WITH THE APPROVED PLAN UPON SUBMISSION OF THE THIRD QUARTER WATER MONITORING DATA.

9. PROTECTION OF ENVIRONMENTAL VALUES: BIG GAME HUNTING SEASON HAS OPENED & THE SITE HAS BEEN ACCESSED BY THE PUBLIC. ALSO, WOODCUTTING ACTIVITIES HAVE BEEN CONDUCTED ON THE ADJACENT AREAS. HOPEFULLY, THE GENERAL PUBLIC WILL RESPECT FENCES & NOT IMPACT THE SITE.

Copy of report mailed to DAN GUY, BCCC

Copy of report given to SLC FOR JOE HELFRICH, BRIAN SMITH, PFO

Inspector's signature William A. Warmack 9/18/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE