0009

5-23-89
7095

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gph RVS

inspection report

Permit No. INA/015/004
Inspection Date 5/2/89.

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Huntington #4 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut.
Company Official(s) Dan Guy.
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 3/31-4/3-89 Weather conditions Clear/Cool/Dry
Acreage 2600 ☐ Permitted 125 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 125 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 5/2/89

Please number comments to correspond with topics on previous page.

General Comments: The undersigned, and Dan Guy representing Beaver Creek Coal Co. walked the entire upper pad. Also key observations were made on the lower pad. Particular attention was directed to the work completed last fall and summarized below:

Diversion: Diversion on the lower pad are fully functional without noticeable erosion. One segement of the ditch near the topsoil pile was observed and no current problems noted

Sediment Pond: Required records were reviewed and were found in order. Ponds were cleaned last fall, are stable, and at the time of this inspection did not contain water.

Other Sediment Control: Existing silt fences were all replaced last fall and no end or under cutting was observed.

Wildlife: Upper pad shows heavy late winter and spring use by both deer and elk. However, from specific observations the heaviest concentration on the upper pad was by elk.

Revegetation: The seeding & mulching done last fall on both the upper & lower pads has a good start!

Copy of report mailed to SLC: For OSM/DOGM

Copy of report given to Beaver Creek Coal Co. Dan Guy.

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

5/2/89

DOGM/IR-2

an equal opportunity employer

11/86 001049