1-9-89 7095 0014

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/004
Inspection Date 1/3/89

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Huntington #4 ☐ Surface ☒ Underground ☐ Other
County Emery State Utah.
Company Official(s) Dan Guy
State Official(s) Bill Malencik
Time of inspection 8:00 ☒ a.m. ☐ p.m. to ___:___ ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 12/7-8/88 Weather conditions Clear/Cold
Acreage 2600 ☐ Permitted 125 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 125 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 1/3/89

Please number comments to correspond with topics on previous page.

General Comments. A partial inspection was conducted on the Huntington 4 reclaimed mine site. Drove to the mine turnoff in Huntington Canyon, but road/snow conditions made the site inaccessible. Therefore, this inspection can only cover a records review.

Permit. The five year permit expires April 28, 1990. A field amendment was completed on 12/8/88 pertaining to maintenance work. The operator, as requested in the amendment, has submitted a map & a description of the completed work.

Sediment Ponds. Inspection reports for the sediment ponds are of record and dated 3/25/88, 4/26/88, 7/15/88, & 8/5/88. The report for the fourth quarter was not in the file, but made available at the close out & were dated 10/25/88, 11/29/88 & 12/7/88.

Water Monitoring. On 11/29/88 the Division notified the operator that his water monitoring plan/amendment was approved on 11/27/88, involving Little Bear Spring, Sta 4-1-W.

Third quarter water reports were submitted to the Division on 10/31/88. Fourth quarter field stations were checked, but the reports have not been submitted to the Division. The report is being prepared and shall be submitted.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 1/3/89

Please number comments to correspond with topics on previous page.

Subsidence. The operator is responsible to conduct an annual surface subsidence inspection to identify slope failure, subsidence cracks, and other damage. The operator has completed the field work and will submit the report with the annual report.

Copy of report mailed to SLC for: OSM - Brain Smith
DOGM - Joe Helfrich

Copy of report given to Beaver Creek Coal Co - Dan Guy.

" " " filed: PFO

Inspector's signature Tim J Thalencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

1/3/89

DOGM/IR-2

an equal opportunity employer

11/86 001049