0001

Correspondence file
~~ACT/007/018~~
JNA/015/007

SOLDIER CREEK COAL CO.

Telephone (801) 637-6360

P.O. Box I
Price, Utah 84501

January 11, 1983

Mr. John White - Inspector #5
Utah Division of Oil, Gas and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Re: Hidden Valley

Dear John:

Acting on your verbal approval, the topsoil pile has been reshaped to encourage revegetation and reduce erosion. I have not seen the work myself, but H.E. Lowdermilk's foreman assures me the work was performed under D.O.G.M. standards. The portals were covered or fenced to bring them up to the Division's standards. When the needed signs become available, I will install them and inspect the work myself. You are welcome to make your inspection at the same time I do.

Sincerely,

SOLDIER CREEK COAL COMPANY

Scott H. Nordness

Scott H. Nordness
Mine Engineer

SHN/jb

RECEIVED
JAN 13 1983
DIVISION OF
OIL, GAS & MINING