RE 7-23-87

0007

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 7, 1987
10:00 a.m. to 1:00 p.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: INA/015/007
Type of Mining Activity: Underground X Surface ___ Other ___
County: Emery
Company Official (s): None
State Official(s): Wm. J. Malencik, Harold Sandbeck
Partial: X Complete: ___ Date of Last Inspection: June 11, 1987
Weather Conditions: Clear/Warm
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	(X)
3. TOPSOIL	( )	( )	(X)	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	(X)	( )
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	(X)
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	(X)	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	(X)	( )
7. COAL PROCESSING WASTE	( )	( )	(X)	( )
8. NONCOAL WASTE	( )	( )	(X)	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(X)	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	(X)	( )	( )	(X)
14. SUBSIDENCE CONTROL	( )	( )	(X)	( )
15. CESSATION OF OPERATIONS	( )	( )	(X)	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(X)	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	(X)	( )

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: INA/015/007 DATE OF INSPECTION July 7, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

The main sign at the end of the black top road and at permit boundary was missing. A followup phone call to Mr. John Rains, Colton, California, revealed the fact that the sign is currently being updated. The mine company is complying with request to update information on the sign as requested in the inspection report of June 11, 1987. Mr. Rains indicated the updated sign shall be reinstalled shortly and before the next inspection.

13. REVEGETATION:

The vegetal conditions are in substance the same as reported in the June 11, 1987, inspection. The volunteer barley has headed out and is drying. No grass seed heads were observed from the seeding conducted last fall.

GENERAL COMMENT:

The general mine area looks good. It's too early to make a firm evaluation in the success of the seeding. The silt fence is all up and functionable. The silt fence repairs, additional fence posts, top tie wire, and reduction in height have provided the necessary stability.

No significant mine site erosion was observed. Also, all fences are up and no domestic livestock or sign of same were observed.

Copy of this Report:
Mailed to: Donna Griffin, OSM; John Rains, CPC
Given to: Joe Helfrich, DOGM

John Whitehead for

Inspectors Signature and Number: Wm. J. Malencik #26 Date: July 13, 1987