0008

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date June 11, 1987

Permittee/Operator Name California Portland Cement

Business Address 695 South Rancho Avenue

City Colton State Calif. Zip 92324-0514

Mine Hidden Valley. ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Wm. J Malencik & Holland Shepard

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection May 4, 1987 Weather conditions Clear/Warm.

Acreage 960 ☑ Permitted 7 ☑ Disturbed 7 ☑ Regraded 7 ☑ Seeded 7 ☑ Bonded

Enforcement Action None

Other: Correct information on entrance sign

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☐
b. Diversions	☒	☐	☐	☐
c. Sediment ponds and impoundments	☐	☐	☒	☐
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☒	☐	☐	☐
f. Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

LPB

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

[2] Signs & Markers: The entrance sign at the end of the blacktop road does not contain current information. The operators name is shown as Soldier Creek instead of Calif. Portland Cement. The address as Price, Ut instead of Colton, Calif. The balance of the information on the sign is correct ie. MSHA & DOGM permit numbers.

The sign should be changed to reflect correct information on or before July 15, 1987.

[4d] Other sediment control measures ie., silt fences recently repaired are operational and in good shape even though the site has experienced little runoff.

[13] Revegetation ie grass seeding performed late last fall is very spotty. No germination and seedlings were observed at the seeding site adjacent to the entrance sign/end of blacktop road. On the balance of the area ie., below the gate, good crop of weeds exist, especially on lower elevations. Some seedlings (grass) are emerging in the lower weeded areas. The only seedlings observed on the road was in the ripped areas with a higher density in pockets or depressions.

Copy of report mailed to Calif. Portland Cement, Donna Griffin OSM

Copy of report given to Joe Helfrich

Inspector's signature Wm. J. Malencik 6/12/87 No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE