RE 5-28-87

0009

File

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date May 4, 1987

Permittee/Operator Name California Portland Cement

Business Address P.O. Box 1947

City Colton State Calif Zip 92324-0514

Mine Hidden Valley ☐ Surface ☐ Underground ☒ Other

County Emery State

Company Official(s) None Present During Inspection

State Official(s) Bill Malencik

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 4-21-87 Weather conditions Windy/Warm/Clear/Dry

Acreage 960 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date May 4, 1987

Please number comments to correspond with topics on previous page.

Introduction. The purpose of this inspection and report is two-fold ie (1) To ascertain what specific work had been completed in response to NOV 87-11-1-1 dated 4/6/87 and, (2) to complete a partial inspection [4d] Other sediment control measures ie, the silt fence had been repaired and was found to be in satisfactory condition.

From the vehicle tire tracks into the area the work had been performed during a light rain. The work consisted of the following: (1) adding additional steel posts for support, (2) taping the tears and utilizing the existing silt fence, (3) lowering the chicken wire support fence and silt fence, and (4) attaching the silt fence and chicken wire to the steel posts by weaving tie wire the entire length of the silt fence. The silt fence was reburied into the soil surface in those areas where it had become dislodged.

Failure to maintain the silt fence was the NOV issue. According to John Rains all work on silt fence completed 4/29/87

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date May 4, 1987

Please number comments to correspond with topics on previous page.

[9] As related to the "Protection xxx and related environmental values", no domestic livestock nor tracks were observed in the seeded area under fence.

[13] Observation on the "Revegetation" included the following: (1) Seeded & Unfenced area adjacent to blacktop entrance road - no signs of plants and/or seed germination, (2) Road that has been ripped - gate to mine site -- sparse cover of grass seedlings 2"-3" in height and most observed in small depressions, (3) two rehabed steep side slopes - sparse cover and 3"-4" seedlings in height in areas where moisture had accumulated, and (4) moderate slopes & flatter areas - more grass seedlings than areas noted above including weed seedlings. All grass plants were dark green in color and showed no signs of moisture stress.

Copy of report mailed to DONNA GRIFFIN & JOHN RAINS

Copy of report given to JOE HELFRICH & ~~JOHN WHITEHEAD~~

Inspector's signature Tom J. Malencik 5/5/87 No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049