7085 0005

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RYS

inspection report

Permit No. INA/015/007

Inspection Date August 31, 1989

Permittee/Operator Name California Portland Cement

Business Address 695 South Rancho Avenue

City Colton State Calif Zip 92324-0514

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 8:30 ☐ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 7/11/89 Weather conditions Clear/Warm

Acreage 960 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 8/31/89

Please number comments to correspond with topics on previous page.

General Comments: The mine site and surrounding areas have received several high intensity storms since the last inspection. While some concern exists over the storm intensity, nevertheless, the operator advised the Division of his intention to perform maintenance work in order to avoid possible future failure of environmental control measures that may result in adverse action by the Division. Also, he is looking to directing more of the runoff from the two highwall slopes. I request Mr. Paul to consult with the Division hydrologist on his water diversion plans.

Other Sediment Control: Recent storms had tested the silt fences. Its fortunate the silt fences had been constructed to a high standard because the recent storms refilled some sections, however, no end running was observed. The operator is currently in the process of negotiating maintenance work with prospective contractors.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date August 31, 1989

Please number comments to correspond with topics on previous page.

Revegetation. Both the road and the B seam slope were reseeded last fall. It doesnt appear that many seedlings survived the summers drought.

The flood in Ivie Creek destroyed the water gap drift fence. Since no livestock are in the area and the operator has commited to repair the drift fence before cattle graze lands adjoining the mine site no action is recommended.

Copy of report mailed to { CPC/John Rains; SBR Karla Knoop. OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to Price Field Office

Inspector's signature Tim J. Shalinik No. 26.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

9/1/89

DOGM/IR-2

an equal opportunity employer

11/86 001049