4-14-89
7085

0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RUS

inspection report

Permit No. ILU/015/007

Inspection Date April 6, 1989

Permittee/Operator Name California Portland Cement

Business Address 625 South Ranchero Avenue

City Colton State CA Zip 92324-0514

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) None

State Official(s) Bill Wakmack

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 9:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection March 7, 1989 Weather conditions Clear & warm

Acreage 960 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 4/6/89

Please number comments to correspond with topics on previous page.

GENERAL: THE MINE SITE WAS DRY & FREE OF SNOW. CATTLE WERE NOT OBSERVED GRAZING ON THE ADJACENT AREAS. IVIE CREEK WAS flowing.

4d. SEDIMENT CONTROLS: THE RILLING THAT WAS DESCRIBED IN THE REPORT OF 3/7/89 HAS NOT PROGRESSED ANY FURTHER AS OF THIS INSPECTION. HOWEVER, PROTECTIVE MEASURES SHOULD BE CONSIDERED TO PREVENT ADDITIONAL RILLING FROM OCCURRING.

13. REVEGETATION: THE B SEAM FILL SLOPE & THE ACCESS ROAD SHOW NO SIGNS OF NEW VEGETATION AS OF THIS INSPECTION. FORBS & GRASSES HAVE STARTED TO GREEN.

Copy of report mailed to BRIAN SMITH (OSM) JOHN RAINS (CPC), KARLA KNOP (JBR), JOE HELFRICH (DOGM)

Copy of report given to PFO

Inspector's signature William A. Warmack 4/7/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE