0004

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date 10/15/90

Permittee/Operator Name Cal Mat Co.

Business Address 1801 E University Drive

City Phoenix State AZ Zip 85034

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) Karla Knoop (JBR)

State Official(s) Susan M. White

Time of Inspection 11:00 ☐ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 9/27/90 Weather conditions Fair & Warm

Acreage 950 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☑	☐
4. Hydrologic balance				
a – Stream channel diversions	☑	☐	☐	☑
b – Diversions	☑	☐	☐	☐
c – Sediment ponds and impoundments	☐	☐	☑	☐
d – Other sediment control measures	☑	☐	☐	☑
e – Surface and groundwater monitoring	☑	☐	☐	☑
f – Effluent limitations	☐	☐	☑	☐
5. Explosives	☐	☐	☑	☐
6. Development waste and spoil disposal	☐	☐	☑	☐
7. Coal processing waste	☐	☐	☑	☐
8. Noncoal waste	☐	☐	☑	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☑	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☑	☐
12. Backfilling and grading	☑	☐	☐	☐
13. Revegetation	☑	☐	☐	☑
14. Subsidence control	☐	☐	☑	☐
15. Cessation of operations	☑	☐	☐	☐
16. Roads				
– Construction	☐	☐	☑	☐
– Drainage controls	☑	☐	☐	☑
– Surfacing	☐	☐	☑	☐
– Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☐	☐	☑	☐
18. Support facilities and utility installations	☐	☐	☑	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

A seam E side

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 10/15/90

Please number comments to correspond with topics on previous page.

1. Records were reviewed at the Division office. Reclamation Bond is for $68,606 with St. Paul Fire & Marine Ins. Co.

Pam Grubaugh-Littig advised the company 2 weeks ago that no Liability Insurance Policy had been submitted to the Division. Lee Edmonson noted that insurance is in effect, however, Certificate will be sent to the Division soon.

4a. A large flow of water had passed through the rip-rapped stream channel. The channel held up very well.

4d. The silt fences all looked good with very little sediment build-up after rains.

4.e. Water monitoring data for May had been submitted.

13. Although the site is in poor vegetative condition the vegetation is improving. Three Atriplex spp., 2 grass spp. and 2 other shrub spp. were observed on site. The water spreading berms had been breached. These should be repaired to encourage vegetative growth.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. UNA/015/007

Inspection Date 10/15/90

Please number comments to correspond with topics on previous page.

16. The second water bar down from top of road continues to head cut, this requires repair.

Approximatly 5 to 6 water bars up from the bottom of the road, the berm along the road needs to be reestablished to prevent rilling along the slope.

Copy of report mailed to Lee Edmonson/CMC; Karla Knoop/IBR; Brian Smith/OSM

Copy of report given to Joe Helfrich

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer