0006

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jok pgl



9/27/90

# inspection report

Permit No. INA/015/007

Inspection Date 8/21/90

Permittee/Operator Name Cal Mat Co.

Business Address P.O. Box 947

City Colton State Calif Zip 92324

Mine Hidden Valley ☐ Surface ☐ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malencik & Tom Munson

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 7/19/90 Weather conditions Clear/Warm

Acreage 950 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action None

✓ Followup Item ... (Ditch On A Seam)

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☒ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☐ | ☐ | ☒ | ☐ |
| 4. Hydrologic balance | | | | |
| — Stream channel diversions | ☒ | ☐ | ☐ | ☐ |
| — Diversions | ☒ | ☐ | ☐ | ☒ |
| — Sediment ponds and impoundments | ☐ | ☐ | ☒ | ☐ |
| — Other sediment control measures | ☒ | ☐ | ☐ | ☒ |
| — Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| — Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☐ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☐ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☒ | ☐ | ☐ | ☒ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☒ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| — Construction | ☐ | ☐ | ☐ | ☐ |
| — Drainage controls | ☐ | ☐ | ☐ | ☐ |
| — Surfacing | ☐ | ☐ | ☐ | ☐ |
| — Maintenance | ☒ | ☐ | ☐ | ☒ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☐ | ☐ | ☐ | ☐ |

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 8/21/90

Please number comments to correspond with topics on previous page.

Diversion. Upper diversion on the A seam needs to be cleaned. Some flag rock had fallen from the escarpment into the ditch. The ditch is functional. A rock hammer will be needed to break the larger rock slabs. This should be done before the next inspection.

Other Sediment Control. Silt fences were observed on site and were in good condition. It does not appear that either silt fence has had any recent runoff.

Non Coal Waste. The mine site was clean of trash, debris or mine waste.

Road. The fence post barriers were in place. It currently is precluding 4-wheel drive vehicles from driving down to the gate.

CMC: John Rains; JBR Karla Knoop

Copy of report mailed to SLC - OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

8/24/90

DOGM/IR-2

an equal opportunity employer

11/86 001049