0007

get pgl

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ~~INA~~ ACT/015/007

Inspection Date 19 July 1990

Permittee/Operator Name Cal Mat Company

Business Address P.O. Box 947

City Colton State California Zip 92324

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Utah

Company Official(s) None

State Official(s) Jess Kelley, Bill Malencik, John Pappas

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 1 June 1990 Weather conditions Partly Cloudy, Warm

Acreage 950 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☒	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☒	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 19 July 1990

Please number comments to correspond with topics on previous page.

4. Hydrologic Balance -

- Diversions - Ditch at top of "A" slope is functional, but some material has fallen into it from the slope above. This material should be removed before the ditch becomes blocked by additional material.
- Other Sediment Control Measures - The erosion matting over the "B" area has been completely repaired and looks good.

5. Revegetation - Grass on the site is sparse, but is coming up quite well beneath the erosion matting. Some saltbush is making an appearance on the road, but the road is covered mainly by a profuse growth of halogeton. Since halogeton is a noxious and poisonous plant, some future control measures may be required by the Division. This would be done for two reasons: 1) To control a noxious weed; and 2) To prevent competition with introduced, desirable plant species.

Copy of report mailed to John Rains/CMC; Karla Knoop/JBR; Brian Smith/OSM; Joe Helfrich/DOGM

Copy of report given to Price Field Office, DOGM

Inspector's signature Jesse W. Kelley No. 34

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer