0010

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date 4/24/90

Permittee/Operator Name California Portland Cement

Business Address 695 South Rancho Av.

City Colton State Calif Zip 92324

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malenák & Susan White

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 3/23/90 Weather conditions Cloudy/Raining

Acreage 950 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action None

✓ Suggested items

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 4/24/90

Please number comments to correspond with topics on previous page.

General Comments: The mine site and adjoining areas were wet from a general rain. It rained through out the inspection. While there was some puddling of water in depressions, no runoff was taking place in the diversions. It appeared that a vehicle had been driven down the road past the gate and to the undisturbed drainage crossing. If additional vehicles access continues, the operator should consider installing additional barricades.

Signs & Markers: The I.D. sign has been moved to the steel post, however, is at ground level. Four shotgun blasts have taken its tole on the sign the full address is barely visible. Operator should replace the sign.

Other Sediment Control: Since the last inspection, two sections of erosion matting on the B seam have been removed. The two sections are not contiguous. One has been rolled to another segement and the other has been rolled and now lies contiguous to a silt

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 4/24/90

Please number comments to correspond with topics on previous page.

fence adjacent to the undisturbed channel. The operator must replace the erosion control matting. As a suggestion, 12" fastners instead of 6" fastners would hold the matting better. This should be done as soon as possible. Please advise the undersigned when you will be on site to perform the required work.

Revegetation: Some seedling emergence was observed on the mine site. It appeared to be more abundant on areas covered with erosion matting.

The access road appeared to again be a failure as far as seedling emergence. Some salt bush plants were observed.

Road. Road drainage controls that were augment with additional work last fall were fully functional.

Copy of report mailed to { CDC/John Rains; UBR/Karla Knoop; SLC; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to filed PFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

4/30/90

DOGM/IR-2

an equal opportunity employer

11/86 001049