0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

7085
4-9-90

inspection report

Permit No. INA/015/007
Inspection Date March 23, 1990

Permittee/Operator Name California Portland Cement
Business Address 695 South Rancho Av.
City Colton State Calif Zip 92324
Mine Hidden Valley. ☐ Surface ☐ Underground ☐ Other
County Emery State Utt
Company Official(s) None
State Official(s) Bill Malencik
Time of inspection 2:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection Feb 7, 1990 Weather conditions Pt Cloudy / Warm / Windy
Acreage 950 ☒ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 3/23/90

Please number comments to correspond with topics on previous page.

General Comments. Site conditions were dry. Environmental control measures were operational, no significant change from descriptions covered in the 2/7/90 complete inspection on compliance matters, and the mine site held up well over the winter.

Stream Channel Diversion. The stream channel diversion that divides the A & B pads & portals was in good shape. The additional protection placed in the channel where it intersects the access road is fully effective and should protect the channel from a potential headcut.

Other Sediment Control. Silt fences were checked and showed no evidence of short circuiting or an inordinate amount of sediment.

Revegetation. The areas reseeded last fall were checked and no signs of seeding emergence was noted.

Copy of report mailed to { CPC/John Rains; JBR/Karla Knoop. SLC: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to RFO

Inspector's signature M. J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/4/90

DOGM/IR-2

an equal opportunity employer

11/86 001049