0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/007
Inspection Date 12/16/91

Permittee/Operator Name (Cal Mat Co) - Hidden Valley Coal Co.
Business Address 1801 University Drive
City PHOENIX State Arizona Zip 85034
Mine HIDDEN VALLEY ☐ Surface ☒ Underground ☐ Other
County EMERY State UT.
Company Official(s) KARLA KNOPP (JBR)
State Official(s) HENRY SAUER and for a short time Bill Malarsik
Time of inspection 12:00 ☐ a.m. ☐ p.m. to 1:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 11/19/91 Weather conditions Foggy and Cold
Acreage 950 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/007

Inspection Date 12/16/91

Please number comments to correspond with topics on previous page.

4) Hydrologic Balance - Other sediment control measures:
Cross silt fences have been installed perpendicular to the 'B' Seam side of the main silt fence which runs parallel to the main diversion channel. This is an attempt to dissipate the flow along (parallel) the main silt fence.

13) Revegetation - Approximately one and one half rolls of erosion control matting has been installed on the 'B' seam slope.

Additionally, Mrs. Knapp and I discussed the remedial action required for N91-26-8-2. These actions would include revegetating the cut slopes and out slopes of the road and the outslopes of the pads adjacent to Dry Creek. I informed Mrs. Knapp that the objective of reseeding should emphasize, surface roughness, adequate seed-to-soil contact and effective water harvesting techniques (ie. mulch incorporation, erosion control matting, etc.).

Copy of report mailed to Lee Edmonsen (CalMat); Bernie Freeman (OSM)

Copy of report given to Joe Helfrich

Inspector's signature Henry Sauer No. 32

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE