State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Inspection Report

Representatives Present During the Inspection:	
Company	Russell Hardy
Company	Steve Demczak Environmental Scientist III

Permit Number:	**C0150007**
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, May 09, 2006
Start Date/Time:	5/9/2006 2:00:00 PM
End Date/Time:	5/9/2006 3:00:00 PM
Last Inspection:	Tuesday, April 18, 2006

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 80's

InspectionID Report Number: 970

Accepted by: pgrubaug
6/9/2006

Permitee: **CONSOLIDATION COAL CO**
Operator: **CONSOLIDATION COAL CO MID-CONTINENT REGION**
Site: **HIDDEN VALLEY MINE**
Address: **PO BOX 566, SESSER IL 62884**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **RECLAIMED**

Current Acreages

960.00	**Total Permitted**
6.70	**Total Disturbed**
6.70	**Phase I**
	Phase II
	Phase III

Mineral Ownership

- ☐ **Federal**
- ☐ **State**
- ☐ **County**
- ☑ **Fee**
- ☐ **Other**

Types of Operations

- ☑ **Underground**
- ☐ **Surface**
- ☐ **Loadout**
- ☐ **Processing**
- ☐ **Reprocessing**

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit last renewed 1/29/2002. The permit area is 960 acres within T. 23 S. R. 6 E. W1/2 Sec 17 and all of Sec. 18. The Permittee's address is listed on the Reclamation Agreement [12755 Olive Blvd. St Louis Mo] has changed. The corporate headquarter's address should read [1800 Washington Rd., Pittsburgh PA]. The Engineering Office for the western operations is in Sesser, IL. Consolidation Coal Co. Board of Directors has authorized an exploratory engineering study at the Hidden Valley reclaimed site. Both portals will be reopened. The exploration will create a stockpile of topsoil, fill, and coal. Plans for site construction and configuration are simultaneously being discussed.

Inspector's Signature: /S/ **Date** Thursday, June 08, 2006

Steve Demczak, Environmental Scientist III
Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150007
Inspection Type: COMPLETE
Inspection Date: Tuesday, May 09, 2006

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	☑	☐	☑	☐
2.	Signs and Markers	☑	☐	☐	☐
3.	Topsoil	☑	☐	☐	☐
4.a	Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	☐	☑	☐	☐
4.c	Hydrologic Balance: Other Sediment Control Measures	☑	☐	☑	☐
4.d	Hydrologic Balance: Water Monitoring	☑	☐	☑	☐
4.e	Hydrologic Balance: Effluent Limitations	☑	☐	☐	☐
5.	Explosives	☑	☐	☐	☐
6.	Disposal of Excess Spoil, Fills, Benches	☑	☐	☐	☐
7.	Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☐	☐
8.	Noncoal Waste	☑	☐	☑	☐
9.	Protection of Fish, Wildlife and Related Environmental Issues	☑	☐	☐	☐
10.	Slides and Other Damage	☑	☐	☐	☐
11.	Contemporaneous Reclamation	☑	☐	☐	☐
12.	Backfilling And Grading	☑	☐	☐	☐
13.	Revegetation	☑	☐	☐	☐
14.	Subsidence Control	☑	☐	☐	☐
15.	Cessation of Operations	☑	☐	☐	☐
16.a	Roads: Construction, Maintenance, Surfacing	☑	☐	☐	☐
16.b	Roads: Drainage Controls	☑	☐	☐	☐
17.	Other Transportation Facilities	☑	☐	☐	☐
18.	Support Facilities, Utility Installations	☑	☐	☐	☐
19.	AVS Check	☑	☐	☐	☐
20.	Air Quality Permit	☑	☐	☐	☐
21.	Bonding and Insurance	☑	☐	☑	☐
22.	Other	☐	☐	☐	☐

1. Permits, Change, Transfer, Renewal, Sale

The permittee has submitted a major exploration plan to the Division. The exploration plan did not pass the administrative completeness review. The permittee is in the process of meeting completeness.

4.a Hydrologic Balance: Diversions

No water was flowing during the inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences were functioning as designed.

4.d Hydrologic Balance: Water Monitoring

The permittee has to take water samples twice a year for two water sample locations. Consol is required to take samples at upper and lower Ivie Creek during high and low flows. The locations were dry.

8. Noncoal Waste

The area was clear of non-coal waste material.

21. Bonding and Insurance

The insurance is by Steadfast Inc. Co. This policy will expire on October 5, 2006. The Certificate of Insurance form meets the requirements of the R645 Coal Rules. The bonding amount is $90,758.