0002

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

015/009 #5

inspection report

Permit No. Actlors1009

Inspection Date 11-12-87

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1379

City Price State Utah Zip 84501

Mine Trail Mountain #9 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Dean Guy

State Official(s) Dan Duce

Time of inspection 12:00 ☒ a.m. ☐ p.m. to 1:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 10-14-87 Weather conditions Cool and partly cloudy

Acreage 1415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a — Stream channel diversions	☒	☐	☐	☒
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☒
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a — Construction	☐	☐	☐	☐
b — Drainage controls	☐	☐	☐	☐
c — Surfacing	☐	☐	☐	☐
d — Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/004

Inspection Date 11-12-87

Please number comments to correspond with topics on previous page.

1) Permits:
Trail mountain is currently transferring their permits to Beaver Creek Coal Co.

2) Signs and Markers:
The Signs had been changed at the enterance to the permit area to show the ownership change.

4a) Stream channel diversions:
The stream channel below the sediment pond had been reconstructed, due to the county road encrochment. The stream had been piping through the rip-rap, but Trailmtn had corrected the problem.

11) Contemporaneous reclamation:
The area that had been disturbed from construction of Trail mtn culinary water well was to be reseeded during the week of 11-16-87 and 11-20-87.

16d) Roads and Maintenance
Mr Guy was having the surface formen lay gravel on ~~on~~ the area Next to the reconstructed stream channel and county road. This area recieves runoff from the county rd. and should help filter runoff before entering the stream.

Copy of report mailed to ~~Donna Griffin~~ Brian Smith (osm) ~~Allen Whitehead~~ Dan Guy (Trail mtn)

Copy of report given to John whitehead, Joe Helfrich

Inspector's signature Dan Guy 11-20-87 No. 11

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE