006

Jch gm

RAL RESOURCES
Gas & Mining
Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009
Inspection Date October 14, 1987

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. Box 370
City Orangeville State Utah Zip 84537
Mine Trail Mountain #9 Mine ☐ Surface ☒ Underground ☐ Other
County Emery State
Company Official(s) Dan Guy, Allen Childs
State Official(s) Harold G. Sandbeck and Bill Malencik
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 5:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 8/27/87 Weather conditions Cloudy/Rainy
Acreage 1415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☒
f Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☒	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
a Construction	☒	☐	☐	☐
b Drainage controls	☒	☐	☐	☐
c Surfacing	☒	☐	☐	☐
d Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date October 14, 1987

Please number comments to correspond with topics on previous page.

General Comments: Trail Mountain Mine, formally owned by Arch Minerals, was purchased by Beaver Creek Coal Company. The sale was consummated and the permit transfer approval is currently being reviewed by DOGM. The new mine name will be Trail Mountain #9.

1.) Permits: On September 24, 1987, Beaver Creek Coal Company posted the bond and mailed the permit transfer to DOGM. DOGM is reviewing the permit transfer. The NPDES permit was found to be in order.

2.) Signs and Markers: The updated ownership signs will be posted as soon as the signs become available. Perimeter markers were seen during the inspection.

4.c.) Sediment Ponds and Impoundments: The operator submitted plans to DOGM regarding the removal of sediment pond waste. The pond waste has been sampled and found to be nontoxic. Since the mine site has limited space to store waste, the operator requests a timely response.

Copy of report mailed to Dan Guy, BCCC and Brain Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harold D. Sandh October 20, 1987 No. 27

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date October 14, 1987

Please number comments to correspond with topics on previous page.

4.e.) Surface and Groundwater Monitoring: All monitoring records were checked and found to be in compliance.

4.d.) Other Sediment Control Measures: Minor berm maintaince is required on road south of the mine office.

8.) Noncoal Waste: NOV 87-26-2-2, 1 of 2 was issued May 27, 1987 for failure to dispose of waste oil in accordance with the approved permit. The waste oil had been sprayed on the stoker coal, but the permit required that the waste oil be removed and transported offsite to an approved area. At the September 22, 1987 assessment conference, Barbara Roberts questioned whether waste oil is considered a hazardous or toxic waste substance. Since the issuance of NOV 87-26-2-2, 1 of 2, Trail Mountain #9 mine is currently storing the waste oil in 55 gallon drums. The operator requests disposition of this waste issue because the mine site has limited space to store waste oil in 55 gallon drums.

Copy of report mailed to Dan Guy, BCCC and Brain Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harvey D. Sandberg October 20, 1987 No. 27

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE