0025 RE 6-26-87

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009
Inspection Date JUNE 10, 1987

Permittee/Operator Name TRAIL MOUNTAIN ~~MINE~~ COAL
Business Address P.O. BOX 370 ORANGEVILLE, UTAH 84537-0370
City ORANGEVILLE State UTAH Zip 84537-0370
Mine ~~UNDERGROUND~~ TRAIL MTN. MINE ☐ Surface ☑ Underground ☐ Other
County EMERY State UTAH
Company Official(s) —
State Official(s) Bill MALENCIK and PAMELA Grubaugh-Littig
Time of inspection 9:00 ☑ a.m. ☐ p.m. to 9:30 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete
Date of last inspection ____ Weather conditions SUNNY AND WARM
Acreage ~~[illegible]~~ 1415 ☑ Permitted 8.8 ☑ Disturbed ☐ Regraded ☐ Seeded 8.8 ☑ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☑	☐	☐	☑
4. Hydrologic balance				
a. Stream channel diversions	☑	☐	☐	☐
b. Diversions	☑	☐	☐	☑
c. Sediment ponds and impoundments	☐	☐	☐	☐
d. Other sediment control measures	☐	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☑
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date June 10, 1987

Please number comments to correspond with topics on previous page.

3. The revegetated topsoil pile was observed behind the Office building. A five foot fence (net wire with 2-barb) has recently been erected to protect this area.

9. Rainbirds have been installed and are in operation in the fence by the loading area to control dust.

4b. The concrete ditch by the chain link fence is clean and well-maintained.

4a. Inlet to 66" culvert is clean and operable

Copy of report mailed to Donna Griffin (OSM) and Ellen Childs

Copy of report given to Joe Helfrich

Inspector's signature Pamela Grubaugh-Littig No. 20 (6/11/87)

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE