0033

file

gch

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009

Inspection Date 3/25/87

Permittee/Operator Name DIAMOND SHAMROCK COAL UNIT

Business Address P.O. BOX 370

City ORANGEVILLE State UTAH Zip 84537-0370

Mine TRAIL MTN COAL COMPANY ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) ALLEN CHILDS

State Official(s) TOM MUNSON + HOLLAND SHEPHERD

Time of inspection 9:30 ☑ a.m. ☐ p.m. to 10:30 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete

Date of last inspection 2/11/87 Weather conditions FAIR + CLEAR

Acreage ☒ Permitted 773.5 ☒ Disturbed 8.8 ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 3/25/87

Please number comments to correspond with topics on previous page.

4. Diversions - The disturbed runoff drains along the fence delineating the permit boundary. Minor erosion was noted along the disturbed edge of the concrete ditch. Some hand work to prevent the concrete ditch from being undercut was recommended. It currently is not a problem but may become one if the erosion becomes severe enough. All disturbed runoff still enters the pond in an adequate fashion.

Sediment ponds and impoundments - The sediment was cleaned out recently and the material removed is situated adjacent to the pond. It has been tested and the results of the test are currently being analyzed for toxicity.

Copy of report mailed to Donna Griffin, Allen Childs

Copy of report given to Joe Helfrich

Inspector's signature John Whitehead for Tom Munson No. #25

04-22-87

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049