12-22-88 7145 0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009
Inspection Date 12/14/88

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) J Alan Childs
State Official(s) Bill Malencik, Rick Smith
Time of inspection 10:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 11/10/88 Weather conditions Pt. Cloudy/Cold
Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 12/14/88

Please number comments to correspond with topics on previous page.

General Comments. The primary purpose of the instant partial inspection was to followup on previous inspections items, observe environmental control measures, and check on underground mine water sampling stations

On the underground portion of the inspection, the operator and state officials noted herein observed that portion of the mine scheduled to be sealed shortly. He pointed out that all the coal ribs were vertical and showed no evidence of fracturing and/or sloughing

Sediment Pond. A small catchment and a pipe (culvert) has been installed to divert road runoff with coal fines to the sediment pond

Water Monitoring. As previously mentioned the operator notified the division that two mine water sampling points had been sealed off. In lieu thereof they proposed and it was agreed to by

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 12/14/88

Please number comments to correspond with topics on previous page.

the Division that: (1) An in-mine monitoring well will be drilled in NW1/4 SE1/4 Sec. 35, Twp. 17S, R 6E after the area is mined (it has not been mined) and (2) An in-mine dropper is currently being monitored in lieu of one of the sealed off stations. No problems were noted

Noncoal Waste. The dumpsters have now been located on the mine site. In addition a fence with a visual aesthetic screen has been placed about the dumpsters.

Support Facilities. A concrete pad has been installed adjacent to the shop. Also the substation fence has been modified with the addition of an aesthetic visual screen. Also a new guard rail has been installed on a way above the oil tanks. Also, a concrete retainer has been constructed on the oil storage area.

Other. A rock fall/slide occurred on the south side of Cottonwood Creek about 1/4 of a mile below the USES boundary. The slide terminated at the edge of Cottonwood Creek and is not associated with Trail Mtn Mining. It did expose the coal seam.

Beaver Creek Coal Co - Dan Guy.

Copy of report mailed to SLC FOR: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO.

Inspector's signature Tom J. Malmnick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2 12/15/88 an equal opportunity employer 11/86 001049