2-16-89 7145

0005

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009
Inspection Date 11/10/88

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn. #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut.
Company Official(s) Dan Guy.
State Official(s) Bill Malencik
Time of inspection 2:00 ☐ a.m. ☒ p.m. to 5:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 11/1/88 Weather conditions Cloudy/Cool
Acreage 1415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 11/10/88

Please number comments to correspond with topics on previous page.

Permit. The Mid-Term Review on the Trail Mtn #9 Mine is in the final stage of completion. Seven deficiencies or items requiring additional explaination were outlined in the Divisions letter of Oct 12, 1988

Sediment Pond. The mine sediment pond needs to be cleaned. The operator stated he is having trouble securing the services of a contractor. He anticipates performing cleanup & maintenance work on the sediment pond yet this fall.

Non-Coal Waste. Three concrete pads with dumpsters have been installed immediately above the sediment pond. The surplus conveyor belting mentioned in a previous report has been removed. The rollers are scheduled to be removed before the next inspection. A chain link fence with aesthetic slats obfuscating the non-coal waste is on order.

Copy of report mailed to { DAN GUY - BCCC
SLC - OSM/Brian Smith. DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J. Smalenick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

11/14/88

DOGM/IR-2 an equal opportunity employer 11/86 001049