0042

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

John

inspection report

Permit No. ACT/015/009

Inspection Date 2/10/88

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 370

City ORANGEVILLE State UTAH Zip 84537

Mine TRAIL MOUNTAIN #9 ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) DAW GUY

State Official(s) RICHARD SMITH, DAW DUCE

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 9:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/7/88 Weather conditions PARTLY CLOUDY, 25°

Acreage 1415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 2/10/88

Please number comments to correspond with topics on previous page.

3. PAP topsoil test plot data were reviewed and discussed. Division Soil Scientist recommended alternate presentation of these data in forthcoming midterm PAP review.

9. Operator noted that Transformer oil was recently tested for PCBs. Test results indicate oil was under EPA limits for PCBs. Certified TMGS indicating EPA compliance will be installed on transformers.

Copy of report mailed to DAN GUY, BLCC

Copy of report given to BRIAN SMITH, OSM; JOE HELFRICH, DOGM

Inspector's signature Richard V. Smith 2-12-88 No. 19

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE