0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RECEIVED
DEC 28 1989
DIVISION OF
OIL, GAS & MINING

inspection report

Permit No. ACT/015/009

Inspection Date Dec 19, 1989

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Dan Guy

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection _____ Weather conditions _____

Acreage 1415 ☐ Permitted 8.8 ☐ Disturbed ☐ Regraded ☐ Seeded 8.8 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☒
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 12/19/89

Please number comments to correspond with topics on previous page.

Permit. The current permit expires on 2/19/90, The ICR has been completed. Currently the operator and the Division are working on the technical aspects of the renewal.

Required records were received and no problems noted.

Signs & Markers. New ID signs have recently been installed at the main gates.

Sediment Pond. Required pond inspection reports were on file. Pond contained water and mine water has been discharged into the pond as provided in the MRP. Pond was stable.

Other Sediment Control. Silt fences were fully functional and do not require any repairs or sediment removal.

Explosives. The explosives are stored upstream from the office in a storage area. The storage area is signed with appropriate signs for explosives. Further, the steel storage containers are all double locked.

Non Coal Waste. The mine site was relatively clean and non-coal waste was being stored in dumpsters.

Revegetation. The sediment pond showed evidence that the embankment had been recently seeded.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 12/19/89

Please number comments to correspond with topics on previous page.

Road. No significant coal fines were observed on the public road. However, the operator. they are watering the coal pad area when the trucks are loaded. This activity by nature causes an accumulation of fines which the operator must keep in conformance until a new truck loading area can be undertaken.

Copy of report mailed to SLC For: DOGM/Joe Helfrich; OSM/Brian Smith

Copy of report given to BCC/Dan Guy.

Inspector's signature Tim J. Chalmuk No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE