Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

October 25, 1989

TO: Richard V. Smith, Permit Supervisor

FROM: Pamela Grubaugh-Littig, Reclamation Engineer pgl

RE: **Completeness Issues, Beaver Creek Coal Company, Trail Mountain #9 Mine, ACT/015/009, Folder #2, Emery County, Utah**

I have identified several completeness issues that must be addressed:

UMC 771.23 Permit Applications-General Requirements for Format and Contents

(c) The technical data in the PAP must be accompanied by the following:

(1) Names of persons or organizations which collected and analyzed the data;

(2) Dates of collection and analyses; and

(3) Descriptions of methodologies used to collect and analyze the data.

The submittal should be compiled as an appendix for all of this information.

UMC 782.19 Identification of Other Licenses and Permits

(b) Appendix 2-5 (Other Licenses and Permits) does not list the address of the authorities issuing other permits. Please submit this information.

UMC 782.21 Newspaper Advertisement and Proof of Publication

An error is contained in the proposed public notice. In Section 25, T17S, R6E, ...Beginning at a point of SW corner of SW1/4 SE1/4, etc. This should read...."SW corner of NW1/4 SE1/4". Please correct.

UMC 783.24 Maps: General Requirements

(a) The surface ownership map, Plate 4-2, must be corrected, i.e., the USFS ownership is non-contiguous in Section 36 and must be corrected.

UMC 784.23 Operation Plan: Maps and Plans

(b)(3) The bonded area must be shown on an appropriate map.

(c) Plate 3-1, the Surface Facilities Map, must be certified.

djh
AT45/105-106