0019

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jph RUS

inspection report

Permit No. ACT/015/009

Inspection Date Aug. 17, 1989

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State UT Zip 84501

Mine Trail Mountain #9 ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) Dan Guy

State Official(s) Bill Wagnack

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection July 19, 1989 Weather conditions Partly cloudy

Acreage 415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☐
b. Diversions	☒	☐	☐	☐
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☒	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date Aug. 17, 1989

Please number comments to correspond with topics on previous page.

GENERAL: Mr. Dan Guy (BCCC) took part in this partial inspection. Ground conditions were wet & Cottonwood Creek was muddy, indicating recent storm activity. Rain gage reading indicated 1.78" since July 24, 1989.

10. Sed Ponds: Pond was containing water to an elevation just below the oil skimmer of the principal spillway. No problems were observed.

11. Other Sed Controls: A basin has been constructed of rock in the Cottonwood Creek channel (above office) to assist pumping of water to the sprinklers at the coal storage area. Also, PVC pipe has been installed to the lower gate.

Copy of report mailed to Joe Helfrich (DOGM), Brian Smith (OSM), Dan Guy (BCCC)

Copy of report given to PFO

Inspector's signature William A. Warnock 8/17/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE