7145

0021

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh RVS

inspection report

Permit No. ACT/015/009

Inspection Date JULY 19, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UT Zip 84501

Mine TRAIL MOUNTAIN #9 ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) PARK KULPACK

State Official(s) BILL WAKAMACK

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection JUNE 8, 1989 Weather conditions WARM & BREEZY

Acreage 14.15 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date July 19, 1989

Please number comments to correspond with topics on previous page.

GENERAL: MR. PARK KILLPACK ASSISTED THE UNDERSIGNED ON THIS PARTIAL INSPECTION. GROUND CONDITIONS WERE DRY & A SLIGHT BREEZE (UP CANYON) WAS NOTICEABLE.

4c. SEDIMENT PONDS: THE SEDIMENTATION POND HAS BEEN CLEANED & APPEARS TO BE STABLE. NO NEW CONSTRUCTION OR RE-CONSTRUCTION OF THE POND WAS INITIATED DURING CLEANOUT, THEREFORE, RE-CERTIFICATION IS NOT REQUIRED.

16d. ROAD MAINTENANCE: DUE TO THE HOT, DRY SUMMER MONTHS, FLOW LEVEL IN COTTONWOOD CREEK HAS DECREASED. WATER FROM THE CREEK IS USED TO WATER THE ROADWAYS (PAD) ADJACENT TO THE COAL PILES. MR. KILLPACK WAS INSTRUCTED TO MAINTAIN THE SPRINKLER SYSTEM TO ENSURE THAT COAL DUST IS NOT GENERATED DURING THE HAULING & LOADING PROCESS.

Copy of report mailed to Lee Hedrick (DOGM), Brian Smith (OSM), Dan Guy (BLCC)

Copy of report given to PFO

Inspector's signature William A. Warnick 7/21/89 No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE