5-23
7145

0023

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh RVS

inspection report

Permit No. ACT/015/009

Inspection Date MAY 10, 1989

Permittee/Operator Name BEAVER CREEK COAL CO.

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine TRAIL MOUNTAIN #9 ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) KEN FLECK

State Official(s) PAMELA GRUBAUGH-LITIG and BILL MALENCIK

Time of inspection 8:30 ☑ a.m. ☐ p.m. to 12:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection APRIL 11, 1989 AND APRIL 13, 1989 Weather conditions SUNNY-WINDY ≈ 60°

Acreage 1445 ☑ Permitted 8.8 ☑ Disturbed ☐ Regraded ☐ Seeded 8.8 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☑	☐	☐	☑
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☐	☐	☐	☐
c. Sediment ponds and impoundments	☐	☐	☐	☐
d. Other sediment control measures	☑	☐	☐	☑
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☑
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☐	☐	☐	☐
c. Surfacing	☑	☐	☐	☑
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐
19. OTHER	✓			✓

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date MAY 10, 1989

Please number comments to correspond with topics on previous page.

2. Signs and Markers - Perimeter markers, topsoil signs and buffer zone markers are easily visible and properly placed.

3 and 4d. Topsoil - The vegetated topsoil pile (by the portal) is protected by newly-installed silt fence.

8. Noncoal waste - Since my March 1989 inspection, more cleanup has been done. The disturbed area is well-maintained.

16c. Surfacing - Gravel has been applied to the facilities area to minimize dust.

19 OTHER - Sprinklers were spraying the facilities area to minimize dust. The Small Area Exemption (SAE) below the sedimentation pond was approved April 27, 1989.

4d. Two downspouts were cleaned out by Ken Fleck during the inspection (on the upper road).

Copy of report mailed to JOHN KATHMANN/OSM Joe Helfrich/DOGM

Copy of report given to Beaver Creek Coal Company

Inspector's signature [signature] (5/12/89) No. 20

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049