7145 0027

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gpb RUS

inspection report

Permit No. ACT/015/009
Inspection Date 4/11/89

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State
Company Official(s) Day Marshall & Dan Guy.
State Official(s) Bill Malencik
Time of inspection 4/11/89 8:00 ☒ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. 4/13 1p.m to 4p.m. ☐ Partial ☒ Complete
Date of last inspection March 7, 1989 Weather conditions
Acreage 1415 ☐ Permitted 8.8 ☐ Disturbed ☐ Regraded ☐ Seeded 8.8 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☒	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐
19. Other.				

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 4/11/89

Please number comments to correspond with topics on previous page.

General Comments. The field portion of this inspection was made the morning of 4/11/89 and the undersigned was accompanied by Jay Marshall the mine manager. The records review was performed the afternoon on the same day with Dan Guy representing the operator.

Permit DOGM permit was issued 2/19/85, tract II added 4/30/87 and the transfer to Beaver Creek Coal Co. was approved 11/23/87. The mid-term permit was approved and is included as part of the official mine records. Permit expires 2/21/90.

The insurance, bonding & other salient documents associated with the permit were reviewed and no problems were detected.

Signs & Markers. The disturbed perimeter markers show evidence of having been painted recently. Other required signs are in place as specified and/or required.

Topsoil - Topsoil pile was checked was well vegetated and protected by straw bales.

Stream Diversion. The cottonwood & the dry gulch diversions were checked. The culverts were clean and no problems noted.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 4/11/89

Please number comments to correspond with topics on previous page.

Sediment Pond. Records & sediment pond field conditions were checked and no problems noted. The water level was 6' from the emergency level.

Water Monitoring. Records were checked and no problems noted. Lab analysis for recent water sampling has not been returned from the laboratory.

Non Coal Waste. The operator with the installation of dumpsters has made a major improvement on the mine surface appearance. The general appearance represents a big improvement over the past.

Subsidence. Subsidence report coming 4 pages was completed in Oct. 1988 and submitted as part of the annual report.

Other. The undersigned proposed a field amendment for a Small Area Exemption. The area about 132' long 60' wide, containing 0.182 acres reclaimed and containing sediment control measures appears not to have been included as a small area exemption even though the Division approved a Cottonwood channel realignment and contemporaneous plans. Further, all necessary measures required for a small area exemption have been observed on site.

Copy of report mailed to SLC: Joe OSM/Brain Smith, DOGM/Joe Helfrich

Copy of report given to Beaver Creek Coal Co.

Inspector's signature Tom J. Malmnick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/13

DOGM/IR-2 an equal opportunity employer 11/86 001049