3-10-89 7145 0028

RUS
Jch

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009

Inspection Date 2/7/89

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine TRAIL MOUNTAIN #9 ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) PARK KILLPACK, JAY MARSHALL

State Official(s) PAMELA GRUBAUGH-LITTIG & BILL MALENCIK

Time of inspection 8:00 ☑ a.m. ☐ p.m. to 10:30 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete

Date of last inspection 2/1/89 Weather conditions 40° SUNNY; MUDDY

Acreage 1415 ☑ Permitted 8.8 ☑ Disturbed ☐ Regraded ☐ Seeded 8.8 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☐	☐	☐	☐
b – Diversions	☐	☐	☐	☐
c – Sediment ponds and impoundments	☑	☐	☐	☑
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☑	☐	☐	☑
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☑
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☑
19. other				

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 2/7/89

Please number comments to correspond with topics on previous page.

2. SIGNS and MARKERS - ALL OF THE SIGNS ARE MAINTAINED. THE Revegetation test plots are clearly marked. The IDENTIFICATION SIGNS ARE NEW and ~~we~~ easily read.

4e. The 4th quarter water monitoring report was checked and the ~~[illegible]~~ annual water monitoring data for 1989 was sent to the Division, January 25, 1989.

4f. The non-coal waste area is being utilized, i.e. the dumpsters. The entire mine site ~~[illegible]~~ exhibits good housekeeping.

4c. The sedimentation pond will need to be cleaned this summer. The pond is currently operable.

18. Concrete walls have been constructed around the oil tanks.

19. Mining is presently occurring at 1st Left and in North Mains in the Federal Coal Lease.

NOTE: A PVC pipe for the sprinklers (for dust control) will need repair (broke during freezing weather).

Copy of report mailed to OSM/Brian Smith DOGM/Joe Helfrich

Copy of report given to Beaver Creek Coal Co./Don Dry

Inspector's signature PFO Pamela Grubaugh-Littig No. 20

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE