3-6-89
7145

0030

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009
Inspection Date 2/1/89

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Dan Guy.
State Official(s) Bill Malencik
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3: ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 1/19/89 Weather conditions Pt Cloudy/snow covered site
Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded
Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 2/1/89

Please number comments to correspond with topics on previous page.

General Comments. The mine site was snow covered except on areas where snow had been bladed and south facing slopes. No significant runoff underway.

Sediment Pond: The sediment pond was stable contained water that had frozen, and the inlet from the gate discharge was open & functional. Required pond inspections & certifications are part of the official mine records.

Surface & Ground Water: Water monitoring on the required seven stations were timely performed and required records maintained at the mine site

The mine water line has been disconnected ie, the segement that went directly into Cottonwood Creek. The line had frozen the meter removed for repairs and currently the mine water is being diverted into the sediment pond as per standing MRP

Non Coal Waste: The old noncoal waste site has been decommissioned as requested in the last inspection. Some minor cleanup remains

Subsidence Control: Subsidence survey conducted by Bruce Ware and is part of the official mine. The report shall be submitted to the Division as part of the annual report. No problems noted.

Copy of report mailed to SLC For: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to Beaver Creek Coal Co./Dan Guy

" " " PFO.

Inspector's signature Wm. J. Shalenick No. 26.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

2/1/89.