0023

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

pgl gdh

inspection report

Permit No. ACT/015/009
Inspection Date 9/5/90

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Dan Guy.
State Official(s) Bill Malencik
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 7/31/90 Weather conditions Clear/Warm
Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☒
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

pgl

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 9/5/90

Please number comments to correspond with topics on previous page.

General Comments. This partial concentrated on following up on work required in the field and, also, on paperwork work revisions and/or additions. The items were identified in the inspection report of 7/31/90 which was also an oversight inspection by OSM.

Signs & Markers. Disturbed markers were repainted.

Diversions. Ditch designs have been resubmitted to the Division on the ditch next to the haul road. Ditch at the lower gate, the depth was increased by grouted material

Sediment Pond. Updated "as built" drawings with proper certifications have been submitted to the Division

Roads. The operator has reclassified roads as follows:

- Coal Pad changed in part to a primary road.
- Other or remaining roads have been designated ancillary roads
- The primary road drawings and maps have been certified

Vegetation. The operator is required to reseed portions of the disturbed area this fall

Copy of report mailed to BCCC/Dan Guy; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Tim J. Smalnick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

9/10/90

DOGM/IR-2 an equal opportunity employer 11/86 001049