2145

0030

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009

Inspection Date 7/12/90

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address PO BOX 1378

City PRICE State UTAH Zip 84501

Mine TRALL MOUNTAIN #9 ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) DAN GUY

State Official(s) TOM MUNSON

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 10:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 6/12/90 Weather conditions

Acreage 1415 ☒ Permitted 8 ☒ Disturbed ☐ Regraded ☐ Seeded 8 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
C Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☒
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 7/11/90

Please number comments to correspond with topics on previous page.

1) The operator is complying with their UPDES filing requirements and have not failed to file reports in a timely manner

4) c The sediment pond will need to be cleaned this fall and has adequate capacity to treat storm water and sediments. The new graveled pad area for trucks to drive on will help decrease the amount of coal fines entering the pond and consequently cut down on maintenance.

10) A berm was installed on the road above the tipple and no more runoff will leave this area.

18) Water systems were installed on all belt lines to help control fugitive dust.

Copy of report mailed to ~~[illegible]~~ Brian Smith - OSM, Bill Malencik (DOGM), DAN GUY (BCCC)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE