0038

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009
Inspection Date 4/10/90

Permittee/Operator Name BEAVER CREEK COAL COMPANY
Business Address P.O. BOX 1378
City PRICE State UTAH Zip 84501
Mine TRAIL MTN #9 ☐ Surface ☒ Underground ☐ Other
County EMERY State UTAH
Company Official(s) DAN GUY
State Official(s) TOM MUNSON
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 3/20/90 Weather conditions CLEAR
Acreage 1415 ☒ Permitted 8 ☒ Disturbed ☐ Regraded ☐ Seeded 8 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☑	☐	☐	☑
4. Hydrologic balance				
— Stream channel diversions	☑	☐	☐	☐
— Diversions	☑	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☐
— Other sediment control measures	☑	☐	☐	☐
— Surface and groundwater monitoring	☑	☐	☐	☑
— Effluent limitations	☑	☐	☐	☐
5. Explosives	☑	☐	☐	☐
6. Development waste and spoil disposal	☑	☐	☐	☐
7. Coal processing waste	☑	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☑	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☑
12. Backfilling and grading	☑	☐	☐	☐
13. Revegetation	☑	☐	☐	☐
14. Subsidence control	☑	☐	☐	☐
15. Cessation of operations	☑	☐	☐	☐
16. Roads				
— Construction	☑	☐	☐	☐
— Drainage controls	☑	☐	☐	☐
— Surfacing	☑	☐	☐	☐
— Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☑	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 4/10/90

Please number comments to correspond with topics on previous page.

3. TOPSOIL - The operator was asked to modify the silt fence surrounding the topsoil pile to better protect the area from offsite debris such as rocks etc. from the surrounding hillsides

4. Surface + Groundwater monitoring - All records through the last quarter of 1989 were checked and found to be in compliance with the Division's water sampling guidelines and the PAP commitments

✓5. Contemporaneous Reclamation - The small area uphill from the sediment pond will need reseeding and contemporaneous reclamation in the fall. This area was pointed out to the operator and will need to be followed up in the fall to assure completion.
Note: All other permits, licenses, signs, etc. were checked and found in compliance. All followup items were completed.

Copy of report mailed to DAN GUY (BCCC), ~~[illegible]~~ BRIAN SMITH OSM

Copy of report given to JOE HELFRICH (DOGM

Inspector's signature Thomas Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 4/10/90

Please number comments to correspond with topics on previous page.

5) (CONT.) An additional reseeding of the stream buffer zone is recommended during the fall reseeding to obtain better revegetation success in this area.

✓ Follow-up items

Copy of report mailed to

Copy of report given to

Inspector's signature Thomas Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE