
U-024317
U-06039
SL-051221
U-014275
SL-050862
U-7653
U-47977
ML-22509
T. 16 S.
T. 17 S.
U-084923
U-084924
WATER PRODUCING FRACTURE
SL-070645
U-02292
U-083066
U-040151
FEE
U-47978
T. 17 S.
T. 18 S.
R.6 E.
R.7 E.
MINE WORKING
"LONG TERM WATER SOURCES"
LOCATION NO. & DESCRIPTION
TYPE
1 2nd RIGHT XC-39 B
FRACTURE-FAULT
2 3rd NORTH XC-65 DR (TW-10 DRILL HOLE)
HORIZONTAL DRILL HOLE INTO GRABEN AREA
HYDROLOGIC MONITORING WELLS
LOCATION
DCP-1 3rd N XC-8
DCP-3 3rd N XC-55
DCP-4 3rd W XC-29
LEGEND
LOCATION NUMBER
LONG TERM MONITORING LOCATION
PAST MONITORING LOCATION (NOW DRY) 'BI PAST YEAR OF MEASURABLE FLOW
PIEZOMETRIC DRILL HOLE STUDY LOCATION 'BI LAST YEAR OF MEASUREMENT WATER SOURCE TYPE (SEE FIGURE 8 - 1992 HYDROLOGIC MONITORING REPORT)
1 SANDSTONE CHANNEL
2 FAULT
3 JOINTS AND FRACTURES
4a ROOF BOLT HOLE
4b EXPLORATION BORE HOLE
CERTIFY THAT I AM A REGISTERED PROFESSIONAL ENGINEER IN THE STATE OF UTAH AND THE SUBSTANCE OF THIS MAP, PROCEDURE OF ACCURACY OF DEPICTED AND DESCRIBED PROPERTIES AND PLANS AND DESIGNS ACCORDING TO THE BEST OF MY KNOWLEDGE AND BELIEF
J. Blake Webster 11/9/99
AS BLAKE WEBSTER NO. 7728 DATE