0007

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

page 4

inspection report

Permit No. ACT/015/009
Inspection Date 9/12/91

Permittee/Operator Name Mountain Coal Company
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Dan Guy.
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 8/2/91 Weather conditions Clear / Temp 70°
Acreage 1415 ☐ Permitted 8.8 ☐ Disturbed ☐ Regraded ☐ Seeded 8.8 ☐ Bonded
Enforcement Action None
✓ Item for permittee to followup on

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 9/12/91

Please number comments to correspond with topics on previous page.

Signs & Markers. The mine signs still carry the name of Beaver Creek Coal Co. The permittee stated that all paperwork on the name change has been submitted to the Division. When the name change and associated documents are approved by the Division new signs will be installed.

Topsoil. The protection on the topsoil pile adjacent to the portal has been improved. A concrete well has been installed at the lower end.

Diversion. The diversion on the upper parking lot needs to be touched up by regrading. This is the diversion adjacent to the highway & chain link fence.

Sediment Pond. Pond was stable, not discharging and a berm has been erected to better direct pad flow into the pond inlet/diversion.

Other Sediment Control. Sediment control should be provided on the parking lot outslope that does not drain into a sediment pond together with the necessary paperwork to the Division. Interim controls have been provided during construction.

Copy of report mailed to CMSCC/Dan Guy; OSM/~~Bruce Smith~~ Bernie Freeman; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to RFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

9/20/91