
U-024317
FEE
U-06039
SL-051221
U-2810
U-014275
SL-050862
U-024319
U-7653
U-47977
ML-22509
T. 16 S.
T. 17 S.
U-47979
U-084923
SL-064607
-064621
U-084924
WATER PRODUCING FRACTURE
SL-070645
U-02292
DETAILED INFORMATION IS NOT AVAILABLE IN THIS AREA
U-084923
FEE
FEE
DETAILED INFORMATION IS NOT AVAILABLE IN THIS AREA
FEE
FEE
U-083066
U-040151
U-1358
FEE
SL-064900
U-02664
U-044026
FEE
U-47978
T. 17 S.
T. 18 S.
R.6 E.
R.7 E.
MINE WORKINGS UPDATED TO: FEB 29, 1992 KJL
LEGEND
U.P&L.CO. PERMIT BOUNDARY LINE
FEDERAL COAL LEASE BOUNDARY LINE
COAL OUTCROP
FAULTS
SECTION CORNER
FOUND SECTION CORNER
EM-26C
SURFACE DRILL HOLE
(EM-26C = East Mtn. Drill Hole No. 26, C = Carec, R = Rilda)
IN MINE DRILL HOLE (• = Completed, o = Proposed)
ROADS
U-47978
FEDERAL COAL LEASE NUMBER
SANDSTONE ROOF
DIRECTION OF CURRENT
SANDSTONE CHANNEL
(NOT IN DIRECT CONTACT
WITH THE COAL SEAM)
Information contained herein has been reviewed and been found to be true and accurate to the best of my knowledge.
License Issued 9/7/88 and expires 4/30/90.
REGISTERED PROFESSIONAL ENGINEER
NO. 2092
DAVID R. DAVIDSON
OF UTAH