0006

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Opt page

inspection report

Permit No. Act/015/009

Inspection Date October 6, 1992

Permittee/Operator Name Mountain Coal Company.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Trail Mtn. ☐ Surface ☒ Underground ☐ Other

County Emery. State

Company Official(s) Dan Guy - Others; Val Payne, Karl Houskeeper, Harry ha Trentz

State Official(s) Bill Malencik

Time of inspection 8:30 ☐ a.m. ☐ p.m. to 3:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection Sept. 24, 1992 Weather conditions Pt. Cloudy / Windy / Temp 60°

Acreage 1450 ☐ Permitted 945 ☐ Disturbed ☐ Regraded ☐ Seeded 945 ☐ Bonded

Enforcement Action None

Permit Detect ✓ Primary Road
✓ Disturbed Area - Surface Facilities Map.
✓ Suggestions for site improvement - see subsequent pages.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☒
— Drainage controls	☒	☐	☐	☒
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act/015/009

Inspection Date 10/6/92

Please number comments to correspond with topics on previous page.

Permit. A request for a permit transfer was prepared and submitted to the Division on October 5, 1992. The transfer involves the new owner, PacifiCorp.

Signs & Markers. Additional permitee markers should be installed by the operator to supplement existing markers. The disturbed area is shown on two PAP maps. A Division Order is recommended to correct a permit detect since the maps do not depict all areas as approved and marked on the ground. The area not shown on the map is the approved ASCA area lying south and below the sediment pond.

Diversion. A downspout had broken on the upper ancillary road. The downspout hooks on to a 6" culvert. The operator should promptly replace the downspout.

Water Monitoring. Some UPDES monthly records (July & August) were not on file at the office. They were at the contractors office and were at the mine site.

Mine water was discharging as I entered the mine site. I intended to sample the discharge as part of the field inspection. When the inspection progressed

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/009

Inspection Date 10/6/92

Please number comments to correspond with topics on previous page.

to that segment of the mine the discharge had terminated

Protection of fish, Wildlife and Environmental Values

It was suggested by the undersigned that two housekeeping and cleanup be made ie.

(1) Clean the rock dust around the rock dust storage tank.

(2) Clean the oil/water from inside the fuel containment area. The oil is confined including the storage tanks in a concrete enclosure.

(3) Two transformers should be disposed of in accordance with approved procedures on the next scheduled pickup into this general area by a duly authorized agent.

Pending Actions.

The operator has submitted a PAP amendment on a second ~~ASCA~~ BTCA area.

Copy of report mailed to MCC/Dan Guy; PCEO/Val Payne; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J Malenich No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

10/8/92