0014

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

qt pgl

inspection report

Permit No. ACT/015/009
Inspection Date 2/19/92

Permittee/Operator Name Mountain Coal Company
Business Address P.O. BOX 1378
City PRICE State UTAH Zip 84501
Mine TRAIL MOUNTAIN #9 ☐ Surface ☒ Underground ☐ Other
County EMERY State UTAH
Company Official(s) DAN GUY
State Official(s) TOM MUNSON
Time of inspection 8:30 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 1/23/92 Weather conditions SUNNY
Acreage 1415 ☑ Permitted 8.8 ☑ Disturbed ☐ Regraded ☐ Seeded 8.8 ☑ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☒
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☐	☐	☐	☐
e. Surface and groundwater monitoring	☒	☐	☐	☒
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 2/19/92

Please number comments to correspond with topics on previous page.

1 PERMITS - The surety bond and liability insurance is in effect and current.

4 (a) Stream Channel Diversion - The Cottonwood Creek Stream diversion was clear and Cottonwood Creek appeared frozen

(b) Diversions - Large ditch between property and highway was full of snow and no runoff was occuring due to the frozen conditions

c) Sediment Ponds and Impoundments Sediment Pond was clear and contained some water. No discharge was noted.

e) Surface and Groundwater monitoring - a letter from Dan Guy to Ms. Pitting dated February 12, 1992 addressed

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 2/19/92

Please number comments to correspond with topics on previous page.

water quality sampling data. Hugh Klein, division hydrologist reviewed this letter and agreed with its contents.

18. Support Facilities and Utility Installations

The new culinary water system is operational and appears to be an excellent alternative to hauling water. The end product is less than .1 mg/l TSS.

Copy of report mailed to Dan Guy / MTN Coal; Bernie Freedman / OSM

Copy of report ~~given to~~ filed Joe Helfrich / DOGM; Price Field Office / BLM

Inspector's signature Tom Munson No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE