
U-024317
FEE
SL-051221
U-014275
SL-050862
U-024319
U-47979
SL-064607
-064621
S.U.L.A. #284
T. 16 S.
T. 17 S.
SL-070645
U-02292
SL-066116
FEE
U-02664
U-040151
U-1336
SL-064900
U-1358
SL-050033
U-044025
FOREST SERVICE
SPECIAL USE PERMIT
U-47978
T. 17 S.
T. 18 S.
MINE WORKINGS UPDATED TO: MARCH 1, 1995 KJL
LEGEND
UP & LCO PERMIT BOUNDARY LINE
FEDERAL COAL LEASE BOUNDARY LINE
COAL OUTCROP
FAULTS
SECTION CORNER
FOUND SECTION CORNER
SURFACE DRILL HOLE
(EM-26C = East Mm. Drill Hole No.26, C=Cored, R=Rotary)
IN MINE DRILL HOLE (+=Completed, ◦=Proposed)
ROADS
U-47978 FEDERAL COAL LEASE NUMBER
SANDSTONE ROOF
CURRENT DIRECTION
TERM WATER SOURCES"
CRIPTION
TYPE
EXPLORATION BORE HOLE
HORIZONTAL DRILL HOLE INTO GRABEN AREA
LEGEND:
LOCATION NUMBER
LONG TERM MONITORING LOCATION
PAST MONITORING LOCATION (NOW DRY)
@ PAST YEAR OF MEASURABLE FLOW
PIEZOMETRIC DRILL HOLE STUDY LOCATION
(SEE FIGURE 8 - 0982 HYDROLOGIC REPORT)
WATER SOURCE TYPE (SEE FIGURE 8 - 0982 HYDROLOGIC MONITORING REPORT)
SANDSTONE CHANNEL
FAULT
JOINTS AND FRACTURES
ROOF BOLT HOLE
EXPLORATION BORE HOLE
HM-2
EAST MOUNTAIN PROPERTY
EMERY COUNTY, UTAH
BLIND CANYON & COTTONWOOD
IN-MINE
WATER MONITORING LOCATIONS
UTAH POWER & LIGHT COMPANY
MINING DIVISION-SALT LAKE CITY, UTAH 84110
DATE: SEPTEMBER 1982
DRAWN BY: C.B.M.
SCALE: 1" = 1000'
DESIGNED BY:
DRAWING NUMBER
CE-10533-DR
SUPERSEDES CE-10555-DR
1-7-86 UPDATED MINE WORKINGS TO MARCH 1, 1995 KJL
1-26-94 UPDATED MINE WORKINGS TO MARCH 1, 1994 RSR
3-7-93 UPDATED WORKINGS ADDED #78 SOUTH SEALS AND REVISED LEGEND TAL
8-20-92 UPDATED WORKINGS, CHANGED LONG TERM WATER SOURCES, DELETED PAST YEAR OF EXPLORATION BORE HOLE IN AND ADDED MONITORING LOCATION #1 TAL
4/4/91 UPDATED DRILL HOLES, MINE WORKINGS, AND ROOF LITHOLOGY, ADDED WATER PRODUCING FRACTURE & SAMPLING SITE JRG
10-28-85 UPDATED WORKINGS & ADDED HOLES DCP-THRU -4 JRG
7-1-84 ADDED PROPOSED LOADWELL DEWATERING STUDY SITE JRG
DATE REVISIONS BY CHK