0042

File
ACT/015/015
folder No. 3
Copy to Lynn, EV, Rick, Ken
Shannon

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

March 15, 1983

JIM
MAR 22 1983

Mr. James Smith
State of Utah
Natural Resources and Energy
Division of Oil Gas & Mining
4241 State Office Building
Salt Lake City, Utah 84114

Dear Mr. Smith:

Confirming our telephone conversation of March 15, 1983, rock material forming the cliff face paralleling Quitchupah Creek near our office/warehouse facilities has slumped causing partial blockage of the stream. With the increased stream flow anticipated during the spring snow melt, this blockage could result in damage to the berms in this area and possibly overflow of Quitchumpah Creek into the mine yard.

To prevent this Consol intends to remove the rock material from the stream channel. This material will be used for rip-rap along the berms in this area. This project may require breaching the berms in order to reach all the rock material blocking the stream flow. However, berms will be reconstructed immediately upon completion of project.

It is my understanding that this notification and verbal approval is sufficient and the project may be started immediately.

Sincerely,

Ronald G. Thompson

Ronald G. Thompson
Mine Engineer

cc: R. Holbrook

RECEIVED
MAR 16 1983
DIVISION OF
OIL, GAS & MINING