0021

Document Information Form

Mine Number: C/015/015

File Name: Incoming

To: DOGM

From:

Person N/A.

Company UNITED STATES DEPARTMENT OF THE INTERIOR.

Date Sent: AUGUST 24, 1987.

Explanation:

RECLAMATION AND ENFORCEMENT TENDAY NOTICE.

cc:

File in:
C/015, 015, Incoming
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

ACT/015/015

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Number: X - 87 - 02 - 006 - 008 TV 2

Originating Office: OSM
625 Silver SW
Albuquerque, NM 87102
Telephone Number: (505) 766-1486

Ten-Day Notice to the State of Utah

You are notified that, as a result of a federal inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Consolidation Coal Co.
(Or Operator if No Permit)
County: Emery
Mailing Address: PO Box 527 Emery, UT 84522
Permit Number: ACT/015/015
Mine Name: Emery Deep

☐ Surface
■ Underground
☐ Other

(1) NATURE OF VIOLATION AND LOCATION: Operator has failed to post and maintain perimeter markers clearly - mine yard area with possible other areas

Section of State Law, Regulation or Permit Condition believed to have been violated: 817.11(a)(1),(d)

(2) NATURE OF VIOLATION AND LOCATION: Operator has failed to comply with the terms and conditions of the permit (by not constructing a dike properly) - mine yard's dike serving as siltation structure

Section of State Law, Regulation or Permit Condition believed to have been violated: 771.19

NATURE OF VIOLATION AND LOCATION:

Section of State Law, Regulation or Permit Condition believed to have been violated:

Remarks or Recommendations:

File in:
☐ Confidential
☐ Shelf
☐ Expandable
Refer to Record No 0021 Date 8-24-87
In C/015, 015, Incoming
For additional information

RECEIVED
AUG 24 1987
DIVISION OF OIL GAS & MINING

Date of Notice: 08/19/87

C Funk

Print Name and ID: Joe C. Funk 006

Distribution: Original-State's Copy, Blue-Field Office, Yellow-Inspector's Copy

IE-160 (3/81)

ACT/015/015

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Number: X - 87 - 02 - 006 - 008 TV 2

Originating Office: OSM
625 Silver SW
Albuquerque, NM 87102
Telephone Number: (505) 766-1486

Ten-Day Notice to the State of Utah

You are notified that, as a result of a federal inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Consolidation Coal Co.
(Or Operator if No Permit)
County: Emery
Mailing Address: PO Box 527 Emery, UT 84522
Permit Number: ACT/015/015
Mine Name: Emery Deep

☐ Surface
■ Underground
☐ Other

(1) NATURE OF VIOLATION AND LOCATION: Operator has failed to post and maintain perimeter markers clearly - mine yard area with possible other areas

Section of State Law, Regulation or Permit Condition believed to have been violated: 817.11(a)(i),(d)

(2) NATURE OF VIOLATION AND LOCATION: Operator has failed to comply with the terms and conditions of the permit (by not constructing a dike properly) - mine yard's dike serving as siltation structure

Section of State Law, Regulation or Permit Condition believed to have been violated: 771.19

NATURE OF VIOLATION AND LOCATION:

Section of State Law, Regulation or Permit Condition believed to have been violated:

RECEIVED
AUG 24 1987
DIVISION OF OIL GAS & MINING

Remarks or Recommendations:

Date of Notice: 08/19/87

Signature of Authorized Rep.: Joe C Funk

Print Name and ID: Joe C. Funk 006

Distribution: Original-State's Copy, Blue-Field Office, Yellow-Inspector's Copy

IE-160 (3/81)