0002

File

gdt

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No ACT/015/015

Inspection Date 11-3-87

Permittee/Operator Name Consolidation Coal Company

Business Address P.O. Box 527

City Emery State UT Zip 84522

Mine Emery Deep ☐ Surface ☑ Underground ☐ Other

County Emery State UT

Company Official(s) Ron Thompson

State Official(s) Holland Shepherd

Time of inspection 2:30 ☐ a.m. ☑ p.m to 3:30 ☐ a.m. ☑ p.m ☑ Partial ☐ Complete

Date of last inspection 10-6-87 Weather conditions cloudy, cool, wet

Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1 Permits	☐	☐	☐	☐
2 Signs and markers	☐	☐	☐	☐
3 Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☑	☐	☐	☑
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6 Development waste and spoil disposal	☐	☐	☐	☐
7 Coal processing waste	☐	☐	☐	☐
8 Noncoal waste	☐	☐	☐	☐
9 Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10 Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12 Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15 Cessation of operations	☐	☐	☐	☐
16 Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17 Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

ACT/015/015
11-3-87

Pg 2

4.c. Sediment Ponds:
More material needs to be removed from the south edge of pond # 3 on the operators ~~coal~~ southern coal storage yard. Most of the large debris has been removed (metal & timber) however, some still remains near the southwest edge of the pond.

4.d. Other Sediment Controls Measures:
A float valve was stuck open on the operator's ~~water~~ storage tank. ~~water~~ Excess water was draining from the facility. The drainage crosses a disturbed area, meanders along an undefined channel, over the ~~hollow~~ highwall then ~~into~~ ends up in ~~the~~ sediment pond #2. No ~~significant erosion was occurring~~, no compliance problems were evident.

11-10-87 Holland Shepherd #9