5-25-89
7065

0017

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/015

Inspection Date May 16, 1989

Permittee/Operator Name Consolidation Coal Company

Business Address P.O. Box 527

City Emery State Utah Zip 84522

Mine Emery Deep ☐ Surface ☒ Underground ☐ Other

County Emery State Utah

Company Official(s) Chris Jones

State Official(s) Daron Haddock

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection April 18-19, 1989 Weather conditions partly Cloudy, cool

Acreage 5180 ☐ Permitted 40 ☐ Disturbed 2.66 ☐ Regraded 2.66 ☐ Seeded 247 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/015

Inspection Date May 16, 1989

Please number comments to correspond with topics on previous page.

4c. Sediment Ponds & impoundments:

A follow-up on Ten Day Notice X89-02-107-3 part 2 of 3 revealed that certifications for ponds 2 and 3 are now available at the mine site. The certifications done by Registered Professional Engineer, Chris Jones, include a narrative statement certifying the ponds as well as as-built drawings.

9. Protection of fish, wildlife, and related environmental values:

The site of NOV 89-28-5-1 was inspected. The coal material previously on the bank of Christiansen stream has been vacuumed up. The site now looks pretty good and the violation can be terminated when the operator submits a plan to minimize future disturbance to this area. The operator is now conducting a study to determine the best method of controlling wind born coal fines.

Copy of report mailed to

Copy of report given to

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/015

Inspection Date May 16, 1989

Please number comments to correspond with topics on previous page.

18. Support facilities and utility installations:
The power company is laying a buried power cable to the new bore hole 4B3. The cable will run parallel to the pipe line and will be buried in ground that has previously been disturbed while burying the pipeline.
The bore hole should be put into operation soon there after.

Copy of report mailed to Chris Jones (Consol)

Copy of report given to Sue Linner, Joe Helfrich DOGM Brian Smith OSM

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer