0016

015/015 #6

RECEIVED

MAR 11 1992

DIVISION OF
OIL GAS & MINING

Mr. Daron R. Haddock
Permit Supervisor
Division of Oil, Gas, and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1230

09 March, 1992

RE: Emery Temp. Coal Stockpile Inspection Report

Dear Mr. Haddock:

Enclosed is the 1st Qtr. Inspection Form of the Temp. Coal Stockpile, where the waste rock is being stored, at the Emery Mine. The form has been certified by a registered P.E. from our St. Louis office.

If you have any questions please call me at (801) 286-2301.

Sincerely,

Dee L. Bray

Dee L. Bray
Mine Engineer
Emery Mine

attachments: Inspection Form certified by a P.E.

INSPECTION FORM

COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name DEE BRAY Title MINE ENGINEER

Date 2-27-92 Date last inspected 12-3-91

Site Name EMERY TEMP COAL STOCKPILE Mine Name EMERY

Refuse Facility ID # 1211-UT-09-0079-01

Refuse piles---Part A only
Impoundments---Part A and Part B

Part A

1.	Foundation preparation (vegetation, topsoil removal?)	✓ Yes	___ No
2.	Lift Thickness (inches)	___	
3.	Compaction (4 to 6 complete passes)	___ Yes	✓ No
4.	Burning* (specify extent and location)	___ Yes	✓ No
5.	Angle of Slope (degrees)	N/A.	___
6.	Seepage* (specify location, color, & appr. volume	___ Yes	✓ No
7.	Cracks or scarps* (location, size)	___ Yes	✓ No
8.	Major erosion problems* (location and extent)	___ Yes	✓ No
9.	Water impounding against toe*	___ Yes	✓ No

Part B

10.	Embankment freeboard (feet)	___	
11.	___Increase___Decrease in water level (feet)	___ Yes	___ No
12.	Sumps or sinkholes in slurry surface	___ Yes	___ No
13.	Clogging* (pipes, ditches, spillway)	___ Yes	___ No
14.	Trash racks clear and in place	___ Yes	___ No

* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection Category	Comments

ERVIN ANDERSON
062-0038535
REGISTERED PROFESSIONAL ENGINEER OF ILLINOIS

FORM 1

Ervin Anderson 3/4/92